

Aufladen des Akkus im Ausland

Die Form der Steckdosen ist in den verschiedenen Ländern und Regionen unterschiedlich.
Zum Aufladen des Akkus benötigen Sie einen Adapterstecker, der der Form der Steckdose entspricht.

A	B	BF	C	O
				

North America	Europe	Oceania	Middle East
United States A	Iceland C	Australia O	Israel C
Canada A	Ireland C	Guam A	Iran C
Mexico A	United Kingdom B.BF	Tahiti C	Kuwait B.C
	Italy C	Tonga O	Jordan B.BF
Asia	Austria C	New Zealand O	
India B.C.BF	Netherlands C	Fiji O	Africa
Indonesia C	Canary Islands C		Algeria A.B.BF.C
Singapore B.BF	Greece C	Latin	Egypt B.BF.C
Sri Lanka B.C.BF	Switzerland C	Argentina O	Guinea C
Thailand A.BF.C	Sweden C	Colombia A	Kenya B.C
South Korea A.C	Spain A.C	Jamaica A	Zambia B.BF
China A.B.BF.C.O	Denmark C	Chile B.C	Tanzania B.BF
Japan A	Germany C	Haiti A	Republic of South Africa B.C.BF
Nepal C	Norway C	Panama A	Mozambique C
Pakistan B.C	Hungary C	Bahamas A	Morocco C
Bangladesh C	Finland C	Puerto Rico A	
Philippines A.BF.O	France C	Brazil A.C	
Vietnam A.C	Belgium C	Venezuela A	
Hong Kong Special Administrative Region B.BF	Poland B.C	Peru A.C	
Macau Special Administrative Region B.C	Portugal B.C		
Malaysia B.BF.C	Romania C		