

The unit heats up.

This is not a malfunction. (This unit may become warm when used for a long time.)