





## Aufladen des Akkus im Ausland

Die Form der Steckdosen ist in den verschiedenen Ländern und Regionen unterschiedlich.

Zum Aufladen des Akkus benötigen Sie einen Adapterstecker, der der Form der Steckdose entspricht.

A	B	BF	C	O
				

North America		Europe		Oceania		Middle East	
United States	A	Iceland	C	Australia	O	Israel	C
Canada	A	Ireland	C	Guam	A	Iran	C
Mexico	A	United Kingdom	B, BF	Tahiti	C	Kuwait	B, C
Asia		Italy	C	Tonga	O	Jordan	B, BF
India		Austria	C	New Zealand	O	Africa	
Indonesia		Netherlands	C	Fiji	O	Algeria	A, B, BF, C
Singapore		Canary Islands	C	Latin		Egypt	B, BF, C
Sri Lanka		Greece	C	Argentina	O	Guinea	C
Thailand		Switzerland	C	Colombia	A	Kenya	B, C
South Korea		Sweden	C	Chile	B, C	Zambia	B, BF
China		Spain	A, C	Jamaica	A	Tanzania	B, BF
Japan		Denmark	C	Chile	B, C	Republic of South Africa	B, C, BF
Nepal		Germany	C	Haiti	A	Mozambique	C
Pakistan		Norway	C	Panama	A	Morocco	C
Bangladesh		Hungary	C	Bahamas	A		
Philippines		Finland	C	Puerto Rico	A		
Vietnam		France	C	Brazil	A, C		
Hong Kong Special Administrative Region		Belgium	C	Venezuela	A		
Macau Special Administrative Region		Poland	B, C	Peru	A, C		
Malaysia		Portugal	B, C				
		Romania	C				